Oliu-1, Armando

From: DISLER, JONATHAN M. (JON) (JSC-SX) (LM) [jonathan.m.disler1@jsc.nasa.gov]
Sent: Wednesday, January 22, 2003 2:03 PM
To: Armando Oliu (E-mail); BAHR, PATRICIA A. (PAT) (JSC-SJ) (NASA); BARBARA A. CONTE (JSC-DM) (E-mail); Bill Lamkin; BOBBIE G. SWAN (JSC-CA) (E-mail); Brenda Eliason; BRIAN K. BALU (JSC-NC) (E-mail); Carlos Ortiz-Longo; Chris "The Man" Cloudt; Chris Hadfield (E-mail); Chris Lessmann; Christine Boykin; Curt Larsen / MS2; Dan Clements / NC-GH2; David Brown / CB (STS-107); David Moyer / MER Manager (E-mail); DAVID R. BRETZ (JSC-SN) (E-mail); David Rigby / MPS SSM (E-mail); DENA S. HAYNES (JSC-EV) (E-mail); Don Prevett; DONALD L. (DON) MCCORMACK (JSC-MV) (E-mail); Doug White; Douglas Powell (MAF); FRED F. MAYER (JSC-NC) (E-mail); Gail Hargrove Boeing-Houston Imagery Scrn.; Greg Katnik; Gregory Galbreath; GREGORY J. BYRNE (JSC-SN3) (E-mail); JAMES B. (BRITT) WALTERS (JSC-SF2) (E-mail); 'James Feeley' (E-mail); James Walters; JAVIER J. JIMENEZ (JSC-EA) (E-mail); Jeff Goodmark (E-mail); Jene Richart / MS2; Jill Lin; Jim Harder; 'John McKee' (E-mail); John Ventimiglia; JONATHAN M. (JON) DISLER (JSC-SN) (E-mail); Jorge Rivera; Julie Kramer; Karen Alfaro (E-mail); KENNETH L. BROWN (JSC-MV) (E-mail); KEVIN L. CROSBY (JSC-SN) (E-mail); 'L Lohrli' (E-mail); Malcolm Glenn; MARK D. ERMINGER (JSC-NC) (E-mail); Mark Erminger; MARK L. HOLDERMAN (JSC-MS) (E-mail); MARSHA S. IVINS (JSC-CB) (E-mail); MARTINEZ, HUGO E. (JSC-NC) (GHG); Michael Anderson / CB (STS-107); MICHAEL W. SNYDER (JSC-SN) (E-mail); Mike Cagle / Boeing Film Screen; Mike O'farrell; P J. (JEFF) BERTSCH (JSC-DD) (E-mail); Pam Madera (E-mail); PAUL F. DYE (JSC-DA8) (E-mail); PAYNE, ROBERT W. (JSC-SA13) (LM); 'Philip Kopfinger' (E-mail); Philip Peterson / Boeing Film Screen (E-mail); Philip Reid / Boeing Film Screen; PREMKUMAR SAGANTI PhD (JSC-SN) (E-mail); RANDALL W. ADAMS (JSC-MS2) (E-mail); Raymond Jones / Manager Boeing Flt. Syst. Analysis; RAYMOND T. (RAY) SILVESTRI (JSC-DM4) (E-mail); Rick Husband / CB (STS-107); Robbie Robbinson; Robert Page; ROBERT SCHARF (JSC-SN) (E-mail); Robert Speece; ROBERT W. FRICKE JR (JSC-MV) (E-mail); Rodney Rocha / ES2 (E-mail); Rodney Wallace; Rohit Dhawan; Ronald Clayton / MS2; Roy Glanville; Rudy Ramon; SA REP; Sara Brandenburg; Scott Otto; Stephen Frick / CB; Steve Derry; Tom Rieckhoff; Tom Wilson; 'Treith' (E-mail)
Subject: STS-107 Debris Strike and Previous Mission Information - Preliminary

For those that are outside of JSC, the following link should be used to access the information on the STS-107 debris strike:

http://sn-isag.jsc.nasa.gov/shuttleweb/mission_support/sts-107/debris_report/107_debris_report.shtml

Thank you-

> Preliminary - Information, including views on the STS-107 debris strike to
> the left wing can be found at the following web site:
>
> http://sn-isag/shuttleweb/mission_support/sts-107/debris_report/107_debris
> _report.shtml
>
> STS-112 and STS-50 both had debris damage caused by missing TPS from the
> ET forward bipod ramp.
>
> Measurement of the debris size on STS-107 and the debris size seen on
> STS-112 are shown.
>
> Information from previous missions STS-112 and STS-50 are included.
>
> Jon Disler / SX3 - LM
>
>