

STS-112 PRE-LAUNCH PAD DEBRIS INSPECTION REPORT
KSC Debris Team
06 October 2002

The pre-launch inspection of the MLP-3, Pad B FSS and RSS was conducted on 06 October 2002 from 1500 to 1700 hrs EDT.

Two facility items were documented in Appendix K of S0007VL4. They were:

- Loose transformer box cover on North side of 235 Foot Level of FSS.
- Debris in gutter around MLP zero level.

Both items were in work at the conclusion of walkdown. Overall the Launch Pad was in excellent condition.

No vehicle items were noted.

Armando Oliu
NASA-KSC